



PATENT 2557SI-001239/US

IN THE U.S. PATENT AND TRADEMARK OFFICE

Applicant(s):

Jung-hyun LEE et al.

Patent No.:

8,143,660

Application No.:

10/797,046

Group No.:

2811

Certificate

Filed:

March 11, 2004

Examiner:

Ori Nadav

JUN 15 2012

Issued:

March 27, 2012

of Correction

June 13, 2012

Conf. No.:

4688

For:

METHOD FOR MANUFACTURING OXIDE FILM HAVING HIGH DIELECTRIC CONSTANT, CAPACITOR HAVING DIELECTRIC FILM FORMED USING THE METHOD, AND METHOD FOR

MANUFACTURING THE SAME

REQUEST FOR CERTIFICATE OF CORRECTION

Customer Service Window Randolph Building 401 Dulany Street Alexandria, VA 22314

Attn: Certificate of Correction Branch

Sir:

Pursuant to the provisions of 37 C.F.R. § 1.322, please enter the attached Certificate of Correction.

Applicant notes that the spelling of the 2nd named inventor of the invention appearing on the page 1 of U.S. Patent No. 8,143,660 is erroneously printed Burn-seok Seo. The correct spelling of the 2nd inventor's name of the invention should read Bu<u>m</u>-seok Seo. Applicant respectfully submits the Declaration dated July 28, 2004 which notes the correct spelling of the inventors' names.

Since the error noted is believed to be the fault of the Patent and Trademark Office, we are not enclosing the \$100.00 Certificate of Correction fee. If it is found to be to the contrary, please charge our Deposit Account No. 08-0750.

U.S. Patent No. 8,143,660

Attorney Docket No.: 2557SI-001239/US

Page 2 of 2

In view of the foregoing, issuance of the Certificate of Correction is respectfully requested.

Respectfully submitted,

HARNESS, DICKEY & PIERCE, P.L.C.

By:_

John A. Castelland, Reg. No. 35,094

P.O. Box 8910

Reston, Virginia 20195

(703) 668 8000

JAC/sem

Enclosures:

Certificate of Correction (PTO/SB/44)

Copy of Declaration

1479938

UNITED STATES PATENT AND TRADEMARK OFFICE

CERTIFICATE OF CORRECTION

Page <u>1</u> of <u>1</u>

PATENT NO.

8,143,660

APPLICATION NO.: 10/797,046

ISSUE DATE

March 27, 2012

INVENTOR(S)

Jung-hyun LEE et al.

It is certified that an error appears or errors appear in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

(75) Inventors: Jung-hyun Lee, Gyeonggi-do (KR); Bum-seok Seo, Seoul (KR); Yo-sep Min, Gyeonngi-do (KR); Young-jin Cho, Gyeonggi-do (KR)

MAILING ADDRESS OF SENDER (Please do not use customer number below):

Harness, Dickey & Pierce, P.L.C.

P.O. Box 8910

Reston, VA 20195

479940

This collection of information is required by 37 CFR 1.322, 1.323, and 1.324. The information is required to obtain or retain a benefit by the public which is to file (and by the USPTO to process) an application. Confidentiality is governed by 35 U.S.C. 122 and 37 CFR 1.14. This collection is estimated to take 1.0 hour to complete, including gathering, preparing, and submitting the completed application form to the USPTO. Time will vary depending upon the individual case. Any comments on the amount of time you require to complete this form and/or suggestions for reducing this burden, should be sent to the Chief Information Officer, U.S. Patent and Trademark Office, U.S. Department of Commerce, P.O. Box 1450, Alexandria, VA 22313-1450. DO NOT SEND FEES OR COMPLETED FORMS TO THIS ADDRESS. SEND TO: Attention Certificate of Corrections Branch, Commissioner for Patents, P.O. Box 1450, Alexandria, VA 22313-1450.